

Attachment 4– Photos of 9 Bends trail



Debris from trail has filled open swales



Erosion of swale



Obstructed swale



Wash out of trail and debris in swale



Sink hole



Large bank slump creating unstable bank condition





Tree damage and impact



Tree damage